

Source: US Geologic Survey Water Resources Investigations Report 89-4004  
 Water Quality and Supply on Cortina Rancheria, Colusa County, California

**Table 1: Characteristics of selected streams along the west side of the Sacramento Valley**

<b>Gaging Station</b>	<b>Estimated mean annual rainfall (inches)</b>	<b>Drainage Area (mi<sup>2</sup>)</b>	<b>Mean annual flow (ft<sup>3</sup>/sec)</b>	<b>average annual runoff per unit area (in.)</b>
Middle Fork Cottonwood Creek near Ono	40	244	254	14.1
Red Bank Creek near Red Bluff	24	93.5	44.3	6.4
Elder Creek at Gerber	30	136	96.2	9.6
Thomes Creek at Paskenta	45	194	304	21.2
Grindstone Creek near Elk Creek	47	156	193	16.8
Stone Corral Creek near Sites	21	38.2	6.1	2.2
Bear Creek near Rumsey	27	100	44.3	6.0